

Inking Roller Care Program

Ensure wet ink has been removed then start with STEP 1



ALLIED PRESSROOM PRODUCTS
PH: 954 920 0909 PH: 323 266 6250
ABC CHEMICAL CO.LTD.
PH:+4417068800 FX: 01706819554
ABC-ALLIED
PH:+86755272368 FX:+8675527692298

FL/CA. USA
ENGLAND
CHINA

STEP 1: TO REMOVE INGRAINED CONTAMINANTS AND DEGLAZE

Apply *Dynaklean* to top inking roller and allow press to idle for up to 5

Wash up roller train using normal technique and press wash

Finish this step with a water rinse and back off the wash up device

STEP 2: TO REMOVE CALCIUM AND SURFACTANT RESIDUES

Apply *Allied Relief* onto rollers, adding more if needed.

Allow press to idle, apply more as necessary to keep the rollers wet

Bring wash up device into contact and rinse with water.

REPEAT THIS PROCEDURE ON A WEEKLY BASIS

THE INKING ROLLERS ARE NOW CLEAN & CONTAMINANT FREE

Roller maintenance will help ensure a consistent quality of printing.

Once built up calcium's (from paper & some inks) are removed from the roller train, rollers do not harden prematurely.

Once surfactants (from wash and founts) are removed from the roller train, rollers will not over attract water and over emulsify ink.

Nor can surfactants squeeze out of the roller train and adhere onto the plate image to cause blinding issues.